Type	Employer	Location	Supervisor	Valid From	Valid To	Status
Excavation Safety Permit	Venus Construction Company	Northwest detention pond / Northwest detention pond	Mario Ramos Orfil Guzmán	7:00 AM 11/5/2026	5:30 PM 11/9/2026	Expired
Excavation Safety Permit	Venus Construction Company	North Building pad 11-1 / North building	Mario Ramos Orfil Guzmán	7:00 AM 11/9/2026	5:30 PM 11/9/2026	Expired
Excavation Safety Permit	Pavecon Commercial, Ltd	North Building pad 11-1 /	Roy Rivera	6:56 AM 11/9/2026	5:30 PM 11/9/2026	Expired
Excavation Safety Permit	Pavecon Commercial, Ltd	South building Pad A-M 17-12 /	Roy Rivera	6:56 AM 11/9/2026	5:30 PM 11/9/2026	Expired
Excavation Safety Permit	RPM xConstruction, LLC	North Building pad 11-1 /	José Castellanos Rolando Sierra	7:11 AM 11/9/2026	5:30 PM 11/9/2026	Expired Not Stopped
Excavation Safety Permit	RPM xConstruction, LLC	Northwest detention pond /	José Castellanos Rolando Sierra	7:11 AM 11/9/2026	5:30 PM 11/9/2026	Expired Not Stopped