Type	Employer	Location	Supervisor	Valid From	Valid To	Status
PER-152581 LOTO Permit V1.0 (Jose Template) DO NOT DELETE . ATL-West Site Specific	Evans General Contractors LLC	MV-Lock Circut #4 / West of 80MW	(No Nominated Rep)	11:46 AM 12/26/2025	11:46 AM 11/27/2026	Scheduled
PER-152588 LOTO Permit V1.0 (Jose Template) DO NOT DELETE . ATL-West Site Specific	Evans General Contractors LLC	F13 (40MW Exterior Work) / MV Utility Metering cabinet #2	(No Nominated Rep)	11:56 AM 12/26/2025	11:56 AM 11/27/2026	Scheduled
PER-152588 LOTO Permit V1.0 (Jose Template) DO NOT DELETE . ATL-West Site Specific	Evans General Contractors LLC	MV-Lock Circut #2 / MV Utility Metering cabinet #2	(No Nominated Rep)	11:56 AM 12/26/2025	11:56 AM 11/27/2026	Scheduled
PER-152594 LOTO Permit V1.0 (Jose Template) DO NOT DELETE . ATL-West Site Specific	Evans General Contractors LLC	MV-Lock Circut #5 / West of 80 MW	(No Nominated Rep)	12:28 PM 12/26/2025	12:28 PM 11/27/2026	Scheduled
PER-152577 LOTO Permit V1.0 (Jose Template) DO NOT DELETE . ATL-West Site Specific	Evans General Contractors LLC	MV-Lock Circut #3 / West side of 80MW.	(No Nominated Rep)	11:43 AM 12/26/2025	11:44 AM 11/28/2026	Scheduled
PER-152587 LOTO Permit V1.0 (Jose Template) DO NOT DELETE . ATL-West Site Specific	Evans General Contractors LLC	MV-Lock Circut #1 / Greystone MV Utility Metering cabinet #1	(No Nominated Rep)	11:52 AM 12/26/2025	11:52 AM 12/26/2026	Scheduled
Raised Access Floor Work	Mission Critical Interior Solutions	H22 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H9 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H11 (40MW	Adrian Morales Carolita Hill Cristian	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired

Type	Employer	Location	Supervisor	Valid From	Valid To	Status
		Interior Level 1) / Gallery	Hernandez			
Raised Access Floor Work	Mission Critical Interior Solutions	H20 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H6 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H23 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H40 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H31 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H25 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H41 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H1 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H28 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H2 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired

Type	Employer	Location	Supervisor	Valid From	Valid To	Status
Raised Access Floor Work	Mission Critical Interior Solutions	H32 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H15 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H34 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H37 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H27 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H20 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H2.3 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H33 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H16 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H26 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior		Adrian Morales Carolita Hill	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired

Type	Employer	Location	Supervisor	Valid From	Valid To	Status
	Solutions	H10 (40MW Interior Level 1) / Gallery	Cristian Hernandez			
Raised Access Floor Work	Mission Critical Interior Solutions	H1.1 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H8 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H36 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H5 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H24 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H30 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H4 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H7 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H29 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H12 (40MW	Adrian Morales Carolita Hill Cristian	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired

Type	Employer	Location	Supervisor	Valid From	Valid To	Status
		Interior Level 1) / Gallery	Hernandez			
Raised Access Floor Work	Mission Critical Interior Solutions	H3 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H17 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H35 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	h19 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H14 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H21 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H38 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Raised Access Floor Work	Mission Critical Interior Solutions	H2.2 (40MW Interior Level 1) / Gallery	Adrian Morales Carolita Hill Cristian Hernandez	6:07 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H22 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H9 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired

Type	Employer	Location	Supervisor	Valid From	Valid To	Status
Hot Work Permit	Mission Critical Interior Solutions	H11 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H20 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H6 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H23 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H40 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H31 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H25 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H41 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H1 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H28 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior		Adrian Morales Carolita Hill	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired

Type	Employer	Location	Supervisor	Valid From	Valid To	Status
	Solutions	H2 (40MW Interior Level 1) / Hallway	Cristian Hernandez			
Hot Work Permit	Mission Critical Interior Solutions	H32 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H15 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H34 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H37 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H27 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H20 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H2.3 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H33 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H16 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H26 (40MW	Adrian Morales Carolita Hill Cristian	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired

Type	Employer	Location	Supervisor	Valid From	Valid To	Status
		Interior Level 1) / Hallway	Hernandez			
Hot Work Permit	Mission Critical Interior Solutions	H10 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H1.1 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H8 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H36 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H5 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H24 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H30 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H4 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H7 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H29 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired

Type	Employer	Location	Supervisor	Valid From	Valid To	Status
Hot Work Permit	Mission Critical Interior Solutions	H12 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H3 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H17 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H35 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	h19 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H14 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H21 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H38 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Mission Critical Interior Solutions	H2.2 (40MW Interior Level 1) / Hallway	Adrian Morales Carolita Hill Cristian Hernandez	8:13 AM 11/9/2026	3:30 PM 11/9/2026	Expired
Hot Work Permit	Viking industrial, inc	Laydown Area / Viking Connex	Mickey Lash Sandy Nunez Savanah Bennett	6:55 AM 11/9/2026	5:54 PM 11/9/2026	Expired